

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Causeberry's Petrol St Person Seen Ms E Dawson
Address Petrol Filling St, St Germain Walk, Hurts, PE293FG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:
As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y N Satisfactory Y N

Notes:

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y N Satisfactory Y N

Notes:

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y N Satisfactory Y N

Notes:

e) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected Y N Satisfactory Y N

Notes:

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y N Satisfactory Y N

Notes:

Does the site have stage II vapour recovery? Y N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y N

Notes:
New Manager, well run site

Are procedures in place adequate in the event of any leaks or spillages? Y N

Notes:

Inspector *Rephel* Date 24/09/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.