

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise Spaldwick Service St. Person Seen Ms Tracey Harrison
Address High Street Spaldwick PE28 0TP

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

*Inspection conducted on behalf of Rushbyden District Council
site under remediation - Manager has limited knowledge
information / training required to be provided*

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No recorded incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

March

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

*Adv to get site register
organised*

e) STAFF COMPETENCE & TRAINING

No of Staff ☐ No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes:

*Training tests required
8 staff 3 competent persons*

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Labels to be cleared

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: *Manager has limited
knowledge*

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Inspector *[Signature]* Date 18/11/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.