

Environmental Protection Report – Vapour Recovery

Premises BRAMPTON HWT CONNECT Person seen ALAN MCCOY
Address BRAMPTON PE19 8ES

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

V-R inspection report completed for District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No recorded incidents

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

C 250 expires 31/1/2020

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No recorded incidents

d) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y / N

Satisfactory Y / N

Notes

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Bray site. New management
Tanks Vol. to be increased

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

Signed [Signature]

Received by _____

Tel/Email: 01454 784 628

Date/Time: 18/11/19