

Environmental Protection Report – Vapour Recovery

Premises SNOZ HUNTINGDON

Person seen CAMARKE

Address STUCKLEY RD HUNTINGDON

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the
District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

Nothing documented

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

Not seen - to be
forwarded

FOLLOWED UP 4/12/19 COMPLAINT 23/11/18
DATED DUE 30/11/2021

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y / N

Satisfactory Y / N

Notes

Staff records to be reviewed
(training)

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

R.A to be reviewed (although no
changes)

Are procedures in place adequate in the event of any
leaks or spillages? Y / N

Notes

Signed [Signature]

Tel/Email: hannah.stepler / 01554 284628

Received by _____

Date/Time: 14/11/2019

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.