

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Shell Bunkers Person Seen Dawn Raj

Address Great North Road, Bunkers, PC19 5XF

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes: Incident log available.

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes: Test cert 17/10/17

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes: Site register poor  
and in need of improvement.

**d) STAFF COMPETENCE & TRAINING**

No of Staff 8 No Questioned 2

Inspected Y/N Satisfactory Y/N

Notes: Training records in place.

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes: VR connection sign in place  
and locked.

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes: Manager new and only  
been in post 20 days.  
Experienced but needs to  
get familiar with site.

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Signed D B

Tel /Email 01954 284331

Received by [Signature]

Date/Time 5/12/17

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.