

Environmental Protection Report – Vapour Recovery

Premises See St Neots SS. Person seen Mr RALA

Address CAMBRIDGE RD ST NEOTS

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

Site Register

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

STAGE 1 ONLY
CERTIFICATE 20/3/2018

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

Site Register

d) STAFF COMPETENCE & TRAINING

No of Staff 3

No Questioned 2

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

UNASSISTED DELIVERIES.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

SLIGHT FADING BUT
LEGIBLE ALL LOCKED
+ SECURED.

Does the site have stage II vapour recovery? Y / ~~N~~

Notes

NO STAGE II

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / ~~N~~

Notes

Are procedures in place adequate in the event of any leaks or spillages? Y / ~~N~~

Notes

Signed CPG

Tel/Email: 01954 284621

Received by R. R. R.

Date/Time: 29/3/2019.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.