

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise SL Highland Ltd Person Seen Mr S Highland
Address Blenheim Service Station, Station Road Blenheim

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

VR inspection conducted by M.R. Shepherd on behalf of Blenheim District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N Satisfactory Y/N

Notes:

New system Nov 2009

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

e) STAFF COMPETENCE & TRAINING

No of Staff 25 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

competent register needs updating

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

In place don't sell amount to quality

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

well run site

Inspector M.R. SHEPHERD Date 09/03/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislative