

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Dunthorn Service at

Person Seen Mr S Highland

Address St John Road Dunthorn PE28 3PA

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted by H Shepherd on behalf of North York  
District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

Not noted on certificate.

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

DM Petroleum Services Ltd  
VR inspection cert 15/08/13.  
Replaced vents + Tested.

**d) STAFF COMPETENCE & TRAINING**

No of Staff ☐ No Questioned ☒

Inspected Y/N

Satisfactory Y/N

Notes:

8 people do deliveries  
60 deliveries a year.

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Inspected 15/08/13

Does the site have stage II vapour recovery? Y/N ☒

Notes:

Not installed  
Pipe work in place

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Well run site

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Risk assessment.

Signed S H

Tel /Email 01954 284628

Received by S HIGHLAND

Date/Time 29/01/14 K.L.C.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.