

ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Pace Calan Saxon Person Seen Muthukumar
Address Great North Rd, Calan Saxon, Alford PE19 8EJ

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Muthukumar has only been working at Pace Calan Saxon for a short period of time

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N Satisfactory Y/N

Notes:

Copy of certificate not seen, copy requested to be forwarded to office

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded
No maintenance work recorded

e) STAFF COMPETENCE & TRAINING

No of Staff 4 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes:

Bitten English

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: Manager not present

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector [Signature] Date 26/1/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation

Please forward copy of certificate to H.R. Shepherd, Sachville House, Sachville Way, Great Cambovie, CB23 6HZ

01454 284 628