

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises EATON SOLON SERVICE STN

Person Seen MR PERUMAI

Address GREAT NORTH RD

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes: ANY INCIDENTS INPUT
INTO THE INCIDENT
LOG BOOK.

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes: CERTIFICATE SEEN, VALID
UNTIL 31/10/15

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes: SITE REGISTER IN ORDER

d) STAFF COMPETENCE & TRAINING

No of Staff 4

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes: INSPECTED STAFF TRAINING
RECORDS - OK.

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes: CONNECTIONS & SIGNS
GOOD

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: NEW PUMPS IN PLACE FOR
ABOUT 5 WEEKS AT TIME
OF INSP. - NO ISSUES.

Does the site have stage II vapour recovery? Y/N

Notes: -

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes: AS PART OF RISK ASSESSMENT
& MANAGER QUESTIONED ON THE
PROCEDURE - OK

Signed [Signature]

Tel /Email 01954 284 641
john.goodwin@cambridgeshire.gov.uk

Received by P. Ambalagan

Date/Time 4/8/15