ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise Pare Rodwilgs	Person Seen Ur Bhotal Proced
Address Okl Great Worth road,	soutry, Hunts, PE28 52P
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
Weinspechen conducted by Histoplaid Fracting Handleids on behalf of Dishict Carollistoplaid	
	D TESTING OFFICIATE FOR PRESSURE DELIFE
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected N Satisfactory
Notes:	Notes:
Nourcidents	D.M. Pe Waleum Davies Hd 03/11/09
b) LOG BOOK DETAILING MAINTENANCE,	e) STAFF COMPETENCE & TRAINING
EXAMINATION & TESTING, INVENTORY	No of Staff S No Questioned
CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	
	Inspected Y/N Satisfactory Y/N
Inspected Y/N Satisfactory Y/N Notes:	Notes:
Nouncidents	Assisted deliveries
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
SIGNS	Satisfactory Y/N
Inspected YN Satisfactory (YN	Cattoliado, 177
Notes:	Notes:
unable to lift all tank	
taps	
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages?
Notes:	Notes:
Inspector Man in 1194 CHERLESO	Date 3/09/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC