

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises Shell (underwater) Person Seen _____
Address 114 Cambridge Rd 28911

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

Date of next test
31/5/2018

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

Certificate of inspection kept.

d) STAFF COMPETENCE & TRAINING

No of Staff 5 No Questioned ☐

Inspected Y/N _____

Satisfactory Y/N _____

Notes:

Training records not seen

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

Link tags not fitted

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N _____

Notes:

Manager not available
Receptionist not left

Are procedures in place adequate in the event of any leaks or spillages? Y/N _____

Notes:

Approved tanks.

Signed [Signature]

Tel /Email 17/11/2017

Received by _____

Date/Time _____

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.