

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises Nell Tenbaker Person Seen Lichard Dean
Address 114 Cambridge road Tenbaker

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapor recovery inspection conducted on behalf of 16
District Council.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Stage 2 Vapor recovery on
pump 5, 6 - amber has
been reported

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Certificate in folder

d) STAFF COMPETENCE & TRAINING
No of Staff ☒ No Questioned ☒

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Not checked as no 'dense'
present to lift tank tops -
needed on rectification scheme.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Documentation to be organised.
Bury site.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

As per note on sheet.

Signed Quill

Tel /Email 01954 784 628

Received by Moh

Date/Time 5th Dec 2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.