

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

2018-
2019.

Premises Shell Stives Person Seen Macher

Address _____

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

conducted on behalf of District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

CAS next test 30/6/2020

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff ☒ No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email 01954 284 628

Received by Machin MD

Date/Time 6/11/2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.