## ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premises MRH Hunhaude	Person Seen W 1 Charles
Address	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
	district and
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
nspected Y/N Satisfactory Y/N Notes:	Inspected Y/N Satisfactory Y/N Notes:
Noinciant	EdS Inspection a lest
E) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Notes:	Inspected Y/N Satisfactory Y/N Notes:
e) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
nspected Y/N Satisfactory Y/N	Satisfactory
Ties: Amber 116L+ shows it ever (S+2) Example 2 d b = Rixed Carhada Steets hept (4/10/18	
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes: As per mole conserved
Signed	Tel /Email_01954_284_628
Received by J. Fr. Tr.	Date/Time 6/11/2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.