## ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premises Mell Colmarcheste	Person Seen W Gbb18
Address legion Llay Commenchente PEZ9 2XH	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
As a result of the inspection of your premises your attention is drawn to the following matters:	
Vapar recen injection concluded on behalfal the	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes: No incidents whire documented	Notes: 3/17/2018 - date d read test:
Ollinerto	a reat rest
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected N Satisfactor N
Notes: No incidents, rethin documented	Notes:
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes:	Notes: rechlication whice issued
Does the site have stage II vapour recovery? YN	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes:
Signed Signed Beceived by	Tel /Email_0/954_287_638

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.