

ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY

Premises BP St Ives Person Seen Mr J Jones

Address Medleyworth Road St Ives

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery & inspection conducted on 16th June 2018
Current

a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

Nothing added into site
logbook

b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES

Inspected Y/N Satisfactory Y/N

Notes:

Tested 16/3/2018 ~
CO2

c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

Nothing added into
site register

d) STAFF COMPETENCE & TRAINING

No of Staff 17 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

E-learning platform - electronic
records

e) VAPOUR RECOVERY CONNECTIONS &
SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

New pumps

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

No run-through system.

Signed

Received by

Tel /Email 01954 284 628

Date/Time 4th June 2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.