

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Little Hampton Service Station Person Seen Mr N Gump
Address 23-25 London Road Yeading PL7 3NP

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the District Council.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

Stage 1B
Expiry date 9/3/2020
Reister Road Haverham Rd

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

As test certificate is up to 9/3/2020
Please conduct visual examination
re leaks etc annually.

d) STAFF COMPETENCE & TRAINING

No of Staff ☒ No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected ☒ Satisfactory ☒

Notes:

Does the site have stage II vapour recovery? ☒

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

rectification advice issued

for this area

Are procedures in place adequate in the event of any leaks or spillages? ☒

Notes:

Signed [Signature]

Tel /Email 01454 284628

Received by [Signature]

Date/Time 23/8/2018 13:20

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.