

# Environmental Protection Report – Vapour Recovery

Premises Little Hampton

Person seen \_\_\_\_\_

Address Yasley PE7 3NQ

## OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

### a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No documented incidents

### b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

Completed 9/3/17 expires  
9/3/2020

### c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

None recorded since  
9/3/17

### d) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y / N

Satisfactory Y / N

Notes

Training records to be  
updated

### e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

### f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Site being upgraded  
Feb 2020

Are procedures in place adequate in the event of any  
leaks or spillages? Y / N

Notes

As per risk assessment

Signed Oliver Herrick

Tel/Email: 01954 284 628

Received by [Signature]

Date/Time: 29/8/19