

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

Premises KWIK LUBE Garage Person Seen Basim

Address ST NICHOLAS CANNES

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

SITE REGISTER IN PLACE  
AND UP TO DATE

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

TEST CERT 16/1/2018

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

AS ABOVE

**d) STAFF COMPETENCE & TRAINING**

No of Staff 14 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

ALL TRAINING COMPLETE

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

IN PLACE + LEGIBLE

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

SITE WELL RUN  
STOCK RECORD BY FAIRCLANKS

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email alan.earsey@cambridgeshire.gov.uk  
01954 284621

Received by [Signature]

Date/Time 19/1/2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.