

# Environmental Protection Report – Vapour Recovery

Premises Kings Lane Garage Person seen TRACY

Address KINGS LANE ST. NOTTS (Platinum Petroleum)

## OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

### a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

SITE REGISTER IN PLACE

### b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

CERTIFICATE 16/1/18  
STAGE 1 ONLY.

### c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

SITE REGISTER IN PLACE  
DETAILS KEPT.

### d) STAFF COMPETENCE & TRAINING

No of Staff 9

No Questioned 2

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

STAFF TRAINING UP TO DATE

### e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / ~~N~~

Satisfactory Y / ~~N~~

Notes

VR CABLES TAPPED BUT  
LEGIBLE

Does the site have stage II vapour recovery? Y / ~~N~~

Notes

### f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / ~~N~~

Notes

ALL OK.

Are procedures in place adequate in the event of any leaks or spillages? Y / ~~N~~

Notes

Signed APL

Tel/Email: 01954 284621

Received by TRACY

Date/Time: 15/3/2019

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.