Environmental Protection Report – Vapour Recovery

Premises Lings Land Ymay Person seen 1 each	
Address Kings (ANK ST NOT	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection your attention is drawn to the following matters:	
X.	7
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y / N Satisfactory Y / N	Inspected Y / 10 Satisfactory Y / 11
Notes Size beistre in Punc	Notes 13/2/2020
a) LOC BOOK DETAILING MAINTENANCE EVANINATION	TI) STAFF COMPETENCE & TRANSING
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y IN Satisfactory Y IN	Inspected Y /4 Satisfactory Y /1
Notes Site Registra in Porce.	Notes TRAINING UP TO DATE
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y / N Satisfactory Y / N	Satisfactory Y / N
Notes Signs FAODS BUT LEGIBLE	Notes Account
CARCES FIXING IN MINIOUS	
(on site).	
Does the site have stage II vapour recovery? Y / 🕏	Are procedures in place adequate in the event of any
Notes	leaks or spillages? Y / N
Yes, Dur,	Notes
1 1	
-00	alon easer @ combon Doshore gov. c
Signed .	Tel/Email:
Received by FOX	Date/Time: 14/2/2020.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.